

Telephone: (44)01827 255719
Email: distributors@img-limited.co.uk
Industrial Maintenance Group Distributors
Riverside Industrial Estate
Fazeley, Tamworth
Staffordshire. B78 3RW

Steel Stick

1.2

1. IDENTIFICATION OF THE SUBSTANCE / MIXTURE AND OF THE COMPANY / UNDERTAKING

1.1 Product Identifier

Material name : Steel Stick

Product code

Relevant identified uses of the substance or mixture and uses advised against

Product use : Epoxy repair compound

1.3 Details of the supplier of the safety data sheet

Manufacturer/Supplier: IMG Ltd., Unit M

Riverside Industrial Estate

Fazeley

Tamworth B78 3RW

Tel. : 01827 283322 Fax. : 01827 250143

Email (for SDSs) : sales@img-limited.co.uk

1.4 Emergency tel. no. : 01827 283322 (Available from 8.30 - 17.00 hours).

2. HAZARDS IDENTIFICATION

1272/2008/EC: Classification, Labelling and Packaging of Substances and Mixtures (CLP) Regulation.

Physical and Chemical Hazards Not classified

Human health Sk Irrit.2; H315; Sk.Sens.1; H317; Eye Irrit.2; H319; EUH205

Environment Aq.Chronie 3; H412

2.2 Label elements

Labelling according to EC Directives: 1272/2008/EC

Signal word: Warning Contains: Bisphenol A-(Epichlorhydrin) {Reaction product}

Pictograms:



Hazard statements:	H315	Causes skin irritation
--------------------	------	------------------------

H317 May cause an allergic skin reaction.

H319 Causes serious eye irritation.

H412 Harmful to aquatic life with long lasting effects.

Precautionary

statements: P273 Avoid release to the environment.

P280 Wear protective gloves/protective clothing/eye protection/face protection.

P302+352 IF ON SKIN: Wash with plenty of soap and water.
P333+313 If skin irritation or a rash occurs: Get medical advice/attention.

P305+351+338 IF IN EYES: Rinse cautiously with water for several minutes. Remove contact

lenses if present and easy to do – continue rinsing.

P501 Dispose of contents/container in accordance with national regulations.